



The six elastomers with superior oil resistance are found in the top half of the diagram. Elastomers used mainly in non-hydrocarbon applications are found in the bottom half of the diagram. Fluorocarbon, polyurethane and nitrile are repeated because they are also widely used with nonhydrocarbons.